



August 21, 2021

Due to component end-of-life (EOL) SAF is announcing an EOL plan for the CFIP PhoeniX family of radios and IDUs. SAF will continue to support and maintain these products 10 years after last shipment.

We will continue to accept CFIP PhoeniX IDU purchase orders until stock of available components is depleted or December 31st, 2021, whichever comes first.

SAF has already stopped accepting new purchase orders for CFIP PhoeniX ODUs.

The specific part numbers on the current price list affected are:

CFIP PhoeniX IDU: S0GIPB01, S0GIPN01, S0GIPL01, S0GIPK01, S0GIPT01, S0GIFB11, S0GIFN11, S0GIFL11, S0GIFK11, S0GIFT11

CFIP PhoeniX ODU: S04RFR02HA, S04RFR02LA, S04RFR04HA, S04RFR04LA, S04RFR05HA, S04RFR05LA, S04RFR06HA, S04RFR06LA, S04RFR02HB, S04RFR02LB, S04RFR04HB, S04RFR04LB, S04RFR05HB, S04RFR05LB, S04RFR06HB, S04RFR06LB
S06RFU01HA, S06RFU01LA, S06RFU01HB, S06RFU01LB

S06RPR18H, S06RPR18L, S06RPU01HA, S06RPU01LA, S06RPU24HA, S06RPU24LA, S06RPU01HB, S06RPU01LB

S06RFU02HA, S06RFU02LA, S06RFU10HA, S06RFU10LA, S06RFU07HB, S06RFU07LB, S06RFU10HB, S06RFU10LB

S06RPU02HA, S06RPU02LA, S06RPU07HA, S06RPU07LA, S06RPU10HA, S06RPU10LA, S06RPU12HA, S06RPU12LA, S06RPU25HA, S06RPU25LA, S06RPU02HB, S06RPU02LB, S06RPU07HB, S06RPU07LB, S06RPU10HB, S06RPU10LB, S06RPU12HB, S06RPU12LB, S06RPU25HB, S06RPU25LB, S06RPU30HB, S06RPU30LB, S06RPU25HC, S06RPU25LC

S07RFU01HA, S07RFU01LA, S07RFU02HA, S07RFU02LA, S07RFU05HA, S07RFU05LA, S07RFU18HA, S07RFU18LA, S07RFU22HA, S07RFU22LA, S07RFU01HB, S07RFU01LB, S07RFU02HB, S07RFU02LB, S07RFU04HB, S07RFU04LB, S07RFU05HB, S07RFU05LB, S07RFU18HB, S07RFU18LB, S07RFU01HC, S07RFU01LC, S07RFU02HC, S07RFU02LC, S07RFU05HC, S07RFU05LC, S07RFU08HC, S07RFU08LC, S07RFU18HC, S07RFU18LC

S07RPU06H, S07RPU06L, S07RPA29H, S07RPA29L, S07RPA30H, S07RPA30L, S07RPR36H, S07RPR36L, S07RPU01HA, S07RPU01LA, S07RPU02HA, S07RPU02LA, S07RPU05HA, S07RPU05LA, S07RPU08HA, S07RPU08LA, S07RPU09HA, S07RPU09LA, S07RPU14HA, S07RPU14LA, S07RPU16HA, S07RPU16LA, S07RPU17HA, S07RPU17LA, S07RPU18HA, S07RPU18LA, S07RPU20HA, S07RPU20LA, S07RPU23HA, S07RPU23LA, S07RPU50HA, S07RPU50LA, S07RPU54HA, S07RPU54LA, S07RPU01HB, S07RPU01LB, S07RPU02HB, S07RPU02LB, S07RPU04HB, S07RPU04LB, S07RPU05HB, S07RPU05LB, S07RPU08HB, S07RPU08LB, S07RPU09HB, S07RPU09LB, S07RPU14HB, S07RPU14LB, S07RPU17HB, S07RPU17LB, S07RPU18HB, S07RPU18LB, S07RPU20HB, S07RPU20LB, S07RPU23HB, S07RPU23LB, S07RPU01HC, S07RPU01LC, S07RPU02HC, S07RPU02LC, S07RPU03HC, S07RPU03LC, S07RPU05HC, S07RPU05LC, S07RPU08HC, S07RPU08LC,



S07RPU09HC, S07RPU09LC, S07RPU14HC, S07RPU14LC, S07RPU16HC, S07RPU16LC,
S07RPU18HC, S07RPU18LC, S07RPU53HC, S07RPU53LC

S08RFU01HA, S08RFU01LA, S08RFU03HA, S08RFU03LA, S08RFU04HA, S08RFU04LA,
S08RFU06HA, S08RFU06LA, S08RFU03HB, S08RFU03LB, S08RFU04HB, S08RFU04LB,
S08RFU06HB, S08RFU06LB, S08RFU03HC, S08RFU03LC

S08RPU25H, S08RPU25L, S08RPU01HA, S08RPU01LA, S08RPU02HA, S08RPU02LA,
S08RPU03HA, S08RPU03LA, S08RPU05HA, S08RPU05LA, S08RPU06HA, S08RPU06LA,
S08RPU09HA, S08RPU09LA, S08RPU15HA, S08RPU15LA, S08RPU24HA, S08RPU24LA,
S08RPU35HA, S08RPU35LA, S08RPU03HB, S08RPU03LB, S08RPU05HB, S08RPU05LB,
S08RPU06HB, S08RPU06LB, S08RPU24HB, S08RPU24LB, S08RPU03HC, S08RPU03LC,
S08RPU04HC, S08RPU04LC, S08RPU35HC, S08RPU35LC

S10RFU01H, S10RFU01L, S10RFR05HA, S10RFR05LA, S10RFR05HB, S10RFR05LB

S10RPU01H, S10RPU01L, S10RPU04H, S10RPU04L, S10RPR05H, S10RPR05L,
S10RPR06HA, S10RPR06LA, S10RPR07HA, S10RPR07LA, S10RPR06HB, S10RPR06LB,
S10RPR07HB, S10RPR07LB, S10RPR06HC, S10RPR06LC, S10RPR07HC, S10RPR07LC

S11RFU01HA, S11RFU01LA, S11RFU05HA, S11RFU05LA, S11RFU18HA, S11RFU18LA,
S11RFU01HB, S11RFU01LB, S11RFU05HB, S11RFU05LB

S11RPU16H, S11RPU16L, S11RPU01HA, S11RPU01LA, S11RPU05HA, S11RPU05LA,
S11RPU18HA, S11RPU18LA, S11RPU01HB, S11RPU01LB, S11RPU05HB, S11RPU05LB,
S11RPU07HB, S11RPU07LB

S13RFU01HA, S13RFU01LA, S13RFU07HA, S13RFU07LA, S13RFU01HB, S13RFU01LB,
S13RFU07HB, S13RFU07LB

S13RPU01HA, S13RPU01LA, S13RPU05HA, S13RPU05LA, S13RPU13HA, S13RPU13LA,
S13RPR14HA, S13RPR14LA, S13RPU01HB, S13RPU01LB, S13RPU05HB, S13RPU05LB

S13RPU01HA, S13RPU01LA, S13RPU05HA, S13RPU05LA, S13RPU13HA, S13RPU13LA,
S13RPR14HA, S13RPR14LA, S13RPU01HB, S13RPU01LB, S13RPU05HB, S13RPU05LB

S15RPU02H, S15RPU02L, S15RPU13H, S15RPU13L, S15RPU01HA, S15RPU01LA,
S15RPU03HA, S15RPU03LA, S15RPU05HA, S15RPU05LA, S15RPU09HA, S15RPU09LA,
S15RPU14HA, S15RPU14LA, S15RPU16HA, S15RPU16LA, S15RPU01HB, S15RPU01LB,
S15RPU03HB, S15RPU03LB, S15RPU09HB, S15RPU09LB, S15RPU14HB, S15RPU14LB,
S15RPU16HB, S15RPU16LB, S15RPU03HC, S15RPU03LC

S18RFU03H, S18RFU03L, S18RFU01HA, S18RFU01LA, S18RFU05HA, S18RFU05LA,
S18RFU12HA, S18RFU12LA, S18RFU01HB, S18RFU01LB, S18RFU05HB, S18RFU05LB,
S18RFU12HB, S18RFU12LB

S23RFU01H, S23RFU01L, S23RFU09H, S23RFU09L, S23RFU10H, S23RFU10L,
S23RFU02HA, S23RFU02LA, S23RFU03HA, S23RFU03LA, S23RFU02HB, S23RFU02LB,
S23RFU03HB, S23RFU03LB

S26RFU04H, S26RFU04L, S26RFU01HA, S26RFU01LA, S26RFU01HB, S26RFU01LB,
S26RFU05HB, S26RFU05LB

S38RPU02H, S38RPU02L, S38RPU03HA, S38RPU03LA, S38RPU03HB, S38RPU03LB



All predecessor radio part numbers no longer appearing on the price list, and all custom radio part numbers associated with the discontinued CFIP PhoeniX product family are included in this EOL announcement.

Migration Paths: Below are the functional migration paths for the EOL product. The replacement radios and IDUs deliver more capacity and features for the increased price point.

Product name	Migration Path	Notes
CFIP PhoeniX IDU	PhoeniX G2 IDU	Worse system parameters can accrue if used with CFIP PhoeniX ODU. Consult with SAF.
CFIP PhoeniX ODU	PhoeniX G2 ODU	10GHz and 26GHz bands are not available for PhoeniX G2 on the date of announcement.

Migration from CFIP Phoenix ODU to PhoeniX G2 ODU can be performed either at one or both end points. However, it is advised to migrate at both endpoints to benefit from better PhoeniX G2 ODU parameters.

Migration from CFIP PhoeniX IDU to PhoeniX G2 IDU must be performed on both end points simultaneously for proper link operation.

Sincerely,

Yuri Isarov

Director of Sales | SAF Tehnika